

X= -2.9826	X= -.2744
Y= 4.2710	Y= 4.2710
Z= 4.5431	Z= 5.4277
X= -3.3824	X= -.6760
Y= 1.7325	Y= 1.7325
Z= 5.7725	Z= 6.6572

X= -5.3758	X= -3.3966
Y= 2.9282	Y= 2.9282
Z= 3.2099	Z= 5.2592
X= -5.8535	X= -3.8743
Y= .1579	Y= .1589
Z= 3.6727	Z= 5.7220

X= -3.4072	X= -.6990
Y= 1.4245	Y= 1.4245
Z= 5.8428	Z= 6.7275
X= -3.4072	X= -.6990
Y= -1.4245	Y= -1.4245
Z= 5.8428	Z= 6.7275

+ X= 0
 Y= 0
 Z= 0

X= -5.8535	X= -3.8743
Y= -.1579	Y= -.1589
Z= 3.6727	Z= 5.7220
X= -5.3758	X= -3.3966
Y= -2.9282	Y= -2.9282
Z= 3.2099	Z= 5.2592

X= -3.3824	X= -.6760
Y= -1.7325	Y= -1.7325
Z= 5.7725	Z= 6.6572
X= -2.9826	X= -.2744
Y= -4.2710	Y= -4.2710
Z= 4.5431	Z= 5.4277

EXP. 5038 - BAZIN